

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.




FIG.1A

Excimer laser treatment




FIG.1B




FIG.2A

09901320-070904





FIG.2B


09501320.070901



A) laser 193 nm 48 mJ/cm² + Q10



B) laser 193 nm 48 mJ/cm² - Q10



C) untreated

FIG.3

006020-02ET0660

UV dose-response curve




FIG.4

UV treatment




FIG.5A

Excimer laser treatment




FIG.5B




FIG. 6A

Excimer laser treatment




FIG. 6B